

**115-32-10250-2050****ROUTE CORRECTION****Water body name:** [Click here to enter text.](#)**Survey date:** 5/29/2014**Water body number:** 115-32-10250-2050**Species & Lifestage:** COr**Watershed:** Chilkat Inlet**MTR:** C030S058E **Quad:** Skagway B-2**Findings:** This stream should be labeled 115-32-10250-2050 and the stream currently with this number should be re-labeled with a new number.**Recommendations:** Re-assign the appropriate streams per above.

Table 1.-115-32-10250-2050 Survey Data.

Waypoint	Latitude	Longitude	Notes	Sample Effort	Sample Results
44	59.3396	-135.7578	Outlet of culvert crossing Haines hwy		Foot Survey
45	59.3397	-135.7575	Confluence of tributary with mainstem.		Foot Survey
46	59.3395	-135.7573	Stream originates on mountainside.		Foot Survey
47	59.3399	-135.7574	Top of tributary. Needs additional investigation		Foot Survey



Figure 1.—Looking downstream on ditch.



Figure 2.—Barrier falls on ditch at wpt 46.





Figure 3.– 115-32-10250-2050 Route Correction map.